
3-Detector wiring circuit

Additional Sensors can be added by wiring them parallel to the Main Module or to other Sensors.

Important:

All sheild wires or extra conductors inside the cable must be tied together inside each sensor being daisy-chained and landed on Battery Negative (-12vdc) inside the switch machine



RAILWAY TECHNOLOGY INCORPORATED